

# Certificate

Admission to implementation  
of Volkswagen test regulations



by

**Volkswagen AG**  
**Materials technology**

for

**Leitat (Acondicionamiento Tarrasense)**  
**Calle de la Innovacio 2**  
**08225 Terrassa**  
**Spain**

The laboratory service provider **Leitat (Acondicionamiento Tarrasense)** has successfully compared the test procedures listed in the Appendix at the above-mentioned locations or at the aforementioned sub-suppliers with Volkswagen.

This certificate entitles the laboratory service provider to offer the tests listed in the Appendix worldwide as a certified laboratory service provider of Volkswagen **from 15.02.2025 to 14.02.2030**, in accordance with the regulations in the declaration of conformity issued by him.

Wolfsburg, den 06.03.2025

List of test procedures that can be offered to Volkswagen suppliers

Blatt 1 von 1

Service provider: **Leitat (Acondicionamiento Tarrasense)**

Region: **Europa**

Location or subcontracting in the attached location legend



Zertifiziert von  
Volkswagen

### Location legend:

Label	Description of test procedures	Note	Location
1 PV 1200	Vehicle Parts; Testing the Environmental Cycle Resistance (80 °C/-40 °C)		A
2 PV 1303	Non-Metallic Materials; Xenon Arc Light Aging of Vehicle Interior Components		A
3 PV 2005	Vehicle Parts; Testing of Resistance to Environmental Cycle Test		A
4 PV 3952	Plastic Components for the Vehicle Interior; Scratch Resistance Test		A
5 PV 3964	Surfaces in the Passenger Compartment; Testing of Cream Resistance		A
6 PV 3966	PP Components; Stress Whitening Properties (Ball Drop Test)		A
7 PV 3986	Vehicle Parts Made of Plastic; Test for Resistance in Damp Heat Environment		A

Service provider: **Leitat (Acondicionamiento Tarrasense)**

Region: **Europa**

Nr.	Company name	Street	Place	Country
A	Leitat (Acondicionamiento Tarrasense)	Calle de la Innovacio 2	08225 Terrassa	Spain